
COLLEGE OF EASTERN UTAH BUNNEL-DMITRICH ATHLETIC CENTER REROOF

451 EAST 400 NORTH PRICE, UTAH 84501

JULY 12, 2006 **CONSTRUCTION DOCUMENTS**






4110 STATE OFFICE BUILDING / SALT LAKE CITY, UTAH 84114 / 801.538.3018 / www.dfcm.state.ut.us DFCM PROJECT NO. 06016610







SCOTT P. EVANS - ARCHITECT & ASSOCIATES P.C.

108 WEST CENTER STREET / BOUNTIFUL, UTAH 84010 / 801.298.1368 / www.spe-architect.com







KEYED NOTES

- EXTG. BUR WITH GRAVEL TO BE REMOVED & ALL EXTG. INSULATION TO REMAIN & ALL EXTG. WALL/CURB CANTS TO BE REMOVED - REFER TO NEW VS EXTG. DETAIL A1/AE-501.
- NEW MECHANICALLY FASTENED SINGLE PLY MEMBRANE SYSTEM REFER TO NEW VS EXTG. DETAIL A1/AE-501.
- EXTG. PRIMARY & SECONDARY ROOF DRAIN SYSTEMS TO REMAIN -REFER TO DETAIL A2/AE-502.
- EXTG. PLUMBING VENT PIPE (SHOWN AS SOLID CIRCLE TYP) TO REMAIN -PROVIDE EXTENSIONS FOR PIPE AS REQUIRED TO GIVE A MIN. OF 12" FROM TOP OF PIPE TO NEW ROOFING SURFACE - REFER TO DETAIL C1/AE-
- EXTG. MECHANICAL FAN/EXHAUSTER RELIEF AIR VENT TO REMAIN -TEMPORARILY REMOVE UNIT & SET ASIDE FOR REINSTALLATION - RAISE CURB AS REQUIRED TO ACHIEVE 8" MIN. DIM. FROM TOP OF CURB TO SURFACE OF NEW ROOFING - REINSTALL UNIT - REMOVAL & REINSTALLATION OF POWERED UNITS SHALL BE DONE BY QUALIFIED LICENSED MECHANICS ONLY - REFER TO DETAIL B2/AE-501 SIM.
- PROVIDE NEW ROOF-TO-ROOF LADDER PER DETAIL B1/AE-502 PROVIDE NEW 30"X30" FLEXIBLE WALK WAY - SEE SPEC. @ TOP & BOTTOM OF ALL NEW LADDERS - APPROXIMATE ROOF-TO-ROOF HEIGHT IS LISTED NEAR LADDER ON PLAN - F.V. ACTUAL ROOF-TO-ROOF HEIGHT.
- EXTG. CRICKETS TO REMAIN REPAIR TO ORIGINAL STATE IF DAMAGE DURING REMOVAL OF THE BUR.
- EXTG. SLOPED GLASS ROOF (NIC) PROTECT FROM DAMAGE DURING CONSTRUCTION.
- PROVIDE NEW ROOF-TO-ROOF LADDER PER DETAIL B3/AE-502 PROVIDE NEW 30"X30" FLEXIBLE WALK WAY - SEE SPEC. @ TOP & BOTTOM OF ALL NEW LADDERS - APPROXIMATE ROOF-TO-ROOF HEIGHT IS LISTED NEAR LADDER ON PLAN - F.V. ACTUAL ROOF-TO-ROOF HEIGHT.
- ANY LOOSE WIRES ON ROOF NEED TO BE TAKEN TO THE NEAREST PARAPET WALL SIMILAR TO THE WIRES THAT ARE EXTG. ALONG THE TOP PARAPET CAP - MAKE THE NECESSARY SPLICES IN THE COAX CABLES TO GET TO THEM TO THE WALL - CONTRACTOR IS VERIFY WITH THE ARCHITECT & OWNER THAT THE SYSTEM IS FUNCTIONING FULLY AFTER WIRE HAVE BEEN RELOCATED - CONTRACTOR IS TO EMPLOY A LICENSED COMMUTATION SPECIALIST TO VERIFY THAT THE SYSTEM IS WORKING



HITECT'S INFORMATION:

SCOTT P. EVANS ARCHITECT & **ASSOCIATES P.C**

> Telephone - 801.298.1368 Telefax - 801.298.2192 info@spe-architect.com www.spe-architect.com

108 West Center Street

Bountiful, Utah 84010

PROFESSIONAL STAMP:

ASTERN UTAH MITRICH TER REROOF TRICH RERO COLLEGE OF EAS BUNNEL-DN ATHLETIC CENTI

NO. DATE DESCRIPTION


GENERAL NOTES

- EXTG. SLOPE IS IN THE STRUCTURAL & WOOD CRICKETS TYPICAL.
- ALL NEW WOOD THAT COMES IN CONTACT WITH CONCRETE OF MASONRY SHALL BE PRESERVATIVE TREATED.
- REQUIREMENTS OF THE ROOFING SYSTEM MANUFACTURER FOR THE 20 YEAR WARRANTY.
- THE CONTRACTOR IS TO PROVIDE A PROPOSAL FOR THE LOCATION OF THE STAGING AREAS WHICH IS TO BE APPROVED BY THE OWNER AND ARCHITECT - CONTRACTOR'S STAGING AREA IS TO BE PROVIDED WITH A SECURE, LOCKED, 6'-0" TALL TEMPORARY CHAIN LINK FENCE. STAGING AREA SHALL NOT BLOCK DOORS, DOCKS, SIDEWALKS ETC. ALL GAPS IN FENCE TO BE MAINTAINED LESS THAN 4". REMOVE AND SECURE ALL LADDERS AT THE END OF EACH DAY. DUMPSTER MUST BE KEPT IN LOCKED FENCED AREA.
- PROTECT ALL EXISTING IMPROVEMENTS INCLUDING LANDSCAPING,

ROOF #4

IT IS THE CONTRACTORS RESPONSIBILITY TO MEET ALL OF THE

SPRINKLING SYSTEMS, SIDEWALKS, PARKING AREAS, SURROUNDING ROOFS ETC. - ANY DAMAGE TO EXISTING IMPROVEMENTS SHALL BE REPAIRED TO ORIGINAL OR BETTER THAN ORIGINAL CONDITION (TO THE SATISFACTION OF THE OWNER AND ARCHITECT)



AE-102

ROOF #1

ROOF #2

ROOF #3

(A4) KEYPLAN

1" = 60'-0"

